

EAST Search History

10/409,492

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	553	comput\$3 and (error rate same control signal\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 17:58
L2	71	chang\$3 and (transmission power same control signal same error rate)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:02
L3	24	I1 and I2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:02
L4	1502	W-CDMA system	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:02
L5	216	error rate control	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:02
L6	1	I3 and I5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:03
L7	3	I3 and I4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:07
L8	53	adjust\$3 and (transmission power same control signal same error rate)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:08

EAST Search History

L9	23	I3 and I8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:08
L10	55	error rate same TFCI	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:08
L14	414	(increas\$3 or decreas\$3) and (transmission power same signal quality)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:10
L17	5	I9 and (I10 or I14)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:33
L18	28908	714/704 or 714/746 or 714/? or 375/240.27 or 375/148 or 375/? or 370/333 or 370/335 or 370/342 or 370/441 370/216 or 370/229	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:22
L19	138	I14 and I18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:22
L20	4	I19 and I8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:23
L23	44	"6154659"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:54

EAST Search History

L24	3	"6879813"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:34
L25	11	control signal error rate	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 19:13
L26	3	I25 and I1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:48
L27	1	I26 and (I2 or I8)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:49
L28	20	comput\$3 and (error rate same TFCI)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:50
L29	3	(increas\$3 or decreas\$3 or chang\$3) and (transmission power same TFCI error rate)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:53
L30	1	I28 and I29	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:51
L32	1	I26 and (I29 or I28)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:51

EAST Search History

L34	4	I23 and (I14 or I2)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 18:55
L35	365	455/343.1 or 455/343.2 or 455/343.4 or 455/343.5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 19:17
L36	0	I25 and I35	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/04/30 19:17